when
installing
the
temp
sensor
and
external
switch
jump
the
common
ground
lead
to then
ground
plane
(after
scraping
off a
little
solder
mask)