

Tuna Helper][+ T/R Switch

RF Activated

W5USJ drawing 12 Aug 2016

$$P_o = ((0.707 \times V_{pk} \text{ dc}) + 0.3)^2 / R_{load}$$

