

Note 2007.3

Here is a handy dandy 'cheat sheet' for all the connectors and their corresponding functions. Pay particular attention to the I/O function list for the Picaxe pins on connector S1.

Picaxe LOGICAL pin I/O functionality

- 0 - OUT 0 / IROUT / SERIAL OUT
- 1 - OUT 1 / IN 1 / ADC 1
- 2 - OUT 2 / IN 2 / ADC 2 / PWM 2 / TUNE
- 3 - IN 3
- 4 - OUT 3 / IN 4
- 5 - SERIAL IN

